


IMAGE SAMPLE

Modle : MSX2000 series Tomography Syst


Date : 2010/1/18

The comparison between fluoroscopy image and tomography image

Fluoroscopy Image




Tomography Image



(2) Ball position error ϕ 0. 76 BGA

Fluoroscopy image




66kV

35X



Tomography image




72kV

35X

(3) Floating ($\phi 0.54$)

Fluoroscopy Image




62kV

35X



Tomography image




Ball Floating

62kV

35X

(4) Double side mounted BGA (ϕ 0. 76)

Fluorocopy image




64kV

35X



Tomography image




64kV

35X

Abnormal Ball

(5) Lead of the connector

Fluoroscopy image




55kV

20X



Tomography image




75kV

20X

(6) Back file of the QFP

Fluoroscropy image



65kV




35X



Tomography image


70kV

35X



(7) Resistor & Capacitor

Fluoroscopy image




61kV

20X



Tomography image



64kV

20X